Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Î	WASTE MANIFEST			Page 1 of 3. Emergency Response Phone			4. Manifes	4. Manifest Tracking Number 008037569 FLE					
	M		York Street	~		rator's Site Addre	ss (if different th	nan mailing addre	ess)			i han ka	
	Generator's Phone: 6. Transporter 1 Company Name 7. Transporter 2 Company Name				and market	1 Can		U.S. EPA ID Number U.S. EPA ID Number					
	8. Designated Facility Name and Site Address Linears Hambers Love Mountain LLC					U.S. EPAID Number							
	#0355 S County Road 236 Waveneles OK 78660 Facility's Phone: #0501697 3500								9 3 18 3	4 £T			
	9a. HM 9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, II and Packing Group (if any))					10. Containers No. Type		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes			
GENERATOR	X	1.MAGOTT, HAZARUKHS WASTE, SCILIO, N.C.S., & OO2, FO PIGHT					br	EST	. 1	F001 F004	F005	F00:	
- GENE		2.		22						and the state of t			
		3.	-									-	
	-	4.											
			and Additional Information								*******		
												ary	
INT'L		rnational Shipments	Import to U.S.		Export from U.S.	Port of e	ntry/exit:	Act of the Second			6	1 4 .	
ORTER	Transporter signature (for exports only):  17. Transporter Acknowledgment of Receipt of Materials  Transporter 1 Printed/Typed Name  Signature  Month Day Year												
TR ANSPORTER	Transpo	orter 2 Printed/Typed Nam	o .		Signature		Karal .			Mont	h Day	Year	
1 -	18. Discrepancy  18a. Discrepancy Indication Space Quantity Type Residue Partial Rejection Full Reject								ction				
<u></u>	18b. Alternate Facility (or Generator)  Manifest Reference Number:  U.S. EPA ID Number												
DESIGNATED FACILITY	acility's 8c. Sigr	s Phone: nature of Alternate Facility	y (or Generator)	ř.		v		<u></u>		Mon	th Day	Year	
- DESIGN	9. Haza		agement Method Codes (i.e., codes	for hazardous waste treatm	nent, disposal, and red	cycling systems)		4.					
		gnated Facility Owner or ( Typed Name	Operator: Certification of receipt of h	azardous materials covered	by the manifest exce Signature	ot as noted in Iter	m 18a			Monti	n Day	Year	
EPA F	orm 87	700-22 (Rev. 3-05) Pr	evious editions are obsolete.	for and eath accept	l the waste the	- generator	is abiquin	a <sup>r</sup>	GEN	ERATOR	'S INITIA	L COI	

Form Approved. OMB No. 2050-0039

lease	print or type. (Form design	igned for use on elite (12-pitch) typewriter.)			A mark	10.525-1	For	m Approve	ed. OMB N	lo. 2050-00			
	NIFORM HAZARDOUS WASTE MANIFEST	K3DVV, (240040	2. Page 1 of	2. Page 1 of 3. Emergency Response Phone			Tracking I		a majorita	FLE			
Ge	enerator's Phone:	York Street 19 269-7400		Generator's Site Addre	ss (if different th			5					
1	6. Transporter 1 Company Name  7. Transporter 2 Company Name							U.S. EPA ID Number U.S. EPA ID Number					
4	8. Designated Facility Name and Site Address Clean Harbors Lone Mountain LLC 40355 S County Road 236 Waynoka, OK 73660 Facility's Phone. (580) 697-3500							U.S. EPA ID Number  OKD 0 6 5 4 3 8 3 7 6					
9a.				10. Cont	10. Containers  No. Type		12. Unit Wt./Vol.	13. Waste Codes					
X	40'9 (m) 2 il n	ZARDOUS WASTE, SOLID, N.C	S., (F001, F003).		DC	251	V	F001 F004	F002	F003			
)	2.				6.0		1	<i>*</i>					
	3.						1						
	4.		4,750		4		1						
15.	5. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.  I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.  Signature  Month Day Year												
16.1	International Shipments	Y 50 ℃  Import to U.S.	Export from	S. Port of e	ntry/exit:	ben		172	2-5	116			
17. Tran	nsporter signature (for expor Transporter Acknowledgment isporter 1 Printed/Typed Nam isporter 2 Printed/Typed Nam	t of Receipt of Materials ne	Sign:		ving U.S.:			Mo Mo	216	1/5			
18. [	Discrepancy Discrepancy Indication Space	ice Quantity [	Туре	Residue		Partial Rej	ection		Full Re	jection			
Facil	Alternate Facility (or General lity's Phone: Signature of Alternate Facility			Manifest Reference	e Number:	U.S. EPA ID N	lumber	Mc	onth Da	y Year			
4		anagement Method Codes (i.e., codes for hazardo	ous waste treatment, disposal,	and recycling systems)						1			
20. [		r Operator: Certification of receipt of hazardous m	aterials covered by the manife	st except as noted in Ite	m 18a	4.		15	134	12			
	ed/Typed Name	varkinari		ature	1261	HAT		Mo	nth Day	Year.			